



U-axis tools, what !?




(U - CENTER, THU500, THU600)

IKEGAI TECHNICAL CENTER

What is U-axis!?



During rotating tools, NC control can be operated for radius direction.
 Axis to control by NC at 0.001mm unit is named U-axis. (For radius direction.)



	BT40			BT50			
	Standard	With balancer		Standard			With balancer
Stroke (mm)	12.5	12.5	5	15	30	50	50
Max. rotation (rpm)	2000	2500	5000	800	700	500	1500